

**MACHINING PRINCIPLE & MACHINE TOOLS
(MECH 3202)**

Time Allotted : 3 hrs

Full Marks : 70

Figures out of the right margin indicate full marks.

*Candidates are required to answer Group A and
any 5 (five) from Group B to E, taking at least one from each group.*

Candidates are required to give answer in their own words as far as practicable.

**Group – A
(Multiple Choice Type Questions)**

1. Choose the correct alternative for the following: **10 × 1 = 10**
- (i) Right Hand turning tool performs machining by
 - (a) moving right to left
 - (b) moving left to right
 - (c) moving back to front
 - (d) moving front to back.
 - (ii) The master line of the rake surface of a turning tool becomes parallel with the principle cutting edge, when
 - (a) Orthogonal rake angle is zero
 - (b) Normal rake angle is zero
 - (c) Inclination angle is zero
 - (d) Side rake angle is zero.
 - (iii) Positive inclination angle (λ) of a turning tool,
 - (a) keeps the chip perpendicular to cutting edge
 - (b) deviates the chip towards the tool shank
 - (c) deviates the chip away from the tool shank
 - (d) none of these.
 - (iv) In orthogonal turning of a mild steel rod, the chip velocity becomes
 - (a) Lesser than the cutting velocity
 - (b) Equal to the cutting velocity
 - (c) Greater than the cutting velocity
 - (d) Any of the above.
 - (v) In machining, Merchant circle diagram deals with
 - (a) surface finish
 - (b) cutting temperature
 - (c) cutting forces
 - (d) tool life.
 - (vi) Tool force can be measured by an instrument called,
 - (a) anemometer
 - (b) dynamometer
 - (c) extensometer
 - (d) speedometer.
 - (vii) Generatrix in a Gear Hobbing process is,
 - (a) Tracing
 - (b) Forming
 - (c) Enveloping
 - (d) Generation.

- (viii) Flat surfaces are not produced in
(a) Lathe (b) Drilling machine
(c) Shaping machine (d) Milling machine.
- (ix) Both cutting motion and feed motion are imparted to the cutting tool in
(a) Lathe (b) Drilling
(c) Milling machine (d) Shaping machine.
- (x) CNC Machine tool has,
(a) open loop control
(b) closed loop position control
(c) closed loop velocity control
(d) closed loop position and velocity control.

Group – B

2. (a) Define Metal Cutting process. Show with neat sketch different tool angles of a Single point turning tool represented in ASA System.
- (b) A single-point turning tool is specified in ASA as $10^\circ, 12^\circ, 8^\circ, 6^\circ, 15^\circ, 15^\circ, (1/64'')$. Find the Orthogonal rake (γ_o) and inclination angle (λ) of the tool using Master line method.

(2 + 6) + 4 = 12

3. (a) During orthogonal machining of steel with a tool of ORS geometry, $0^\circ, 10^\circ, 8^\circ, 6^\circ, 15^\circ, 60^\circ, 1$ (mm) at a feed of 0.36 mm/rev, the chip thickness was found to be 0.6 mm. Determine (i) chip reduction coefficient, (ii) shear angle and (iii) cutting strain.
- (b) Discuss on the types of chips obtained in turning, mentioning the condition at which they are formed. What types of chips are obtained in milling operation?

6 + (4 + 2) = 12

Group – C

4. (a) Draw the Merchant circle diagram of forces and deduce the following relations,
 $P_s = P_z \cos \beta_o - P_{xy} \sin \beta_o$ and $P_n = P_z \sin \beta_o + P_{xy} \cos \beta_o$,
where P_s & P_n are shear and normal forces acting at the shear plane P_z & P_{xy} are the component of forces acting on the tool in the orthogonal plane
 β_o = shear plane angle
- (b) A ductile metal bar of 120 mm diameter is turned at a speed of 320 rpm, feed 0.24 mm/rev and 3mm depth of cut by a tool of the following ORS geometry : $0^\circ, 10^\circ, 8^\circ, 6^\circ, 20^\circ, 70^\circ, 0$ (mm) and a chip thickness (a_2) of 0.7 mm is obtained. The following observations were made: Tangential force (P_z) = 750 N; Transverse force (P_y) = 200 N. Determine (i) shear force (ii) normal force at shear plane (iii) Cutting power consumption.

6 + (2 + 2 + 2) = 12

B.TECH/ME/6TH SEM/MECH 3202(BACKLOG)/2021

5. (a) What are the different methods of failure of cutting tools? Show with a graph the flank wear growth of a turning tool with machining time. Express Taylor's Tool Life equation mentioning the parameters involved.
- (b) Write down the essential properties of a Tool material used in machining. Discuss on the salient properties of HSS and Cemented Tungsten Carbide as cutting tool materials.

(2 + 2 + 2) + (2 + 4) = 12

Group – D

6. (a) What are the major components of a machine tool? How does drilling machine produce internal cylindrical surface by their tool-work motion as well as generatrix and directrix.
- (b) What are the classification criteria according to degree of automation and type of automation? What are the specifications of a centre lathe?

(2 + 4) + (3 + 3) = 12

7. (a) Draw the kinematic structure of a centre lathe.
- (b) How would you specify a milling machine? Write down two different operations that can be performed using a milling machine (give necessary sketches).
- (c) Explain how 12 TPI thread can be cut with a 4TPI lead screw in a centre lathe.

3 + (2 + 4) + 3 = 12

Group – E

8. (a) What is machinability? How is it assessed or quantified?
- (b) Describe a Ray diagram mentioning its purpose.
- (c) Explain with the help of a kinematic diagram the feed change system of a Centre Lathe.

(1 + 2) + 3 + 6 = 12

9. (a) Determine the actual machining time required to reduce the diameter of a rod from 200 mm to 150 mm over a length of 200 mm at cutting velocity of 200 m/min and feed of 0.3 mm/rev. Assume approach length of 5 mm and overrun length of 5 mm.
- (b) How is "closed loop control" different from "open loop control"? Explain in reference to numerical control of tool-work motions in machine tools with neat sketch.

6 + 6 = 12

Department & Section	Submission Link
ME	https://classroom.google.com/c/MzY5NDczMDEwMzUz?cjc=p5u75ui